[31.375437] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 7
[31.375439] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[31.375440] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[31.375441] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[31.375442] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[31.375443] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[31.375444] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[31.375445] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[31.375446] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[31.375447] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[31.375448] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[31.375450] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[31.375451] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[31.375452] iwlwifi 0000:03:00.0: 0x00200405 | last host cmd
[31.375453] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[31.375456] ieee80211 phy8: Hardware restart was requested
[31.375463] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[31.375468] CPU: 2 PID: 612 Comm: NetworkManager Tainted: P   W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[31.375468] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[31.375469] Call Trace:
[31.375475] dump_stack+0x5c/0x85
[31.375481] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[31.375484] ? remove_wait_queue+0x60/0x60
[31.375489] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[31.375494] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[31.375498] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[31.375502] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[31.375505] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[31.375507] ? preempt_count_add+0x56/0xa0
[31.375511] __iwl_mvm_mac_start+0x2d5/0x350 [iwlmvm]
[31.375514] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[31.375526] drv_start+0x35/0x110 [mac80211]
[31.375536] ieee80211_do_open+0x302/0x8f0 [mac80211]
[31.375544] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[31.375547] __dev_open+0xc2/0x140
[31.375549] ? _raw_spin_lock_bh+0x13/0x40
[31.375551] __dev_change_flags+0x1a7/0x1e0
[31.375553] dev_change_flags+0x23/0x60
[31.375555] do_setlink+0x324/0xcc0
[31.375558] ? __kmalloc_reserve.isra.37+0x2e/0x80
[31.375559] ? pskb_expand_head+0xe1/0x2b0
[31.375561] ? ___cache_free+0x31/0x2e0
[31.375563] ? __local_bh_enable_ip+0x3f/0x70
[31.375564] ? inet6_fill_ifla6_attrs+0x451/0x470
[31.375566] rtnl_newlink+0x7f6/0x920
[31.375568] ? sock_def_readable+0xe/0x70
[31.375570] ? __netlink_sendskb+0x47/0x60
[31.375574] ? ttwu_stat+0x110/0x120
[31.375575] ? _raw_write_unlock_bh+0x20/0x20
[31.375577] ? security_capable+0x41/0x60
[31.375579] rtnetlink_rcv_msg+0x17e/0x2b0

```
[    31.375581]  ? rtnl_calcit.isra.26+0x120/0x120
[    31.375583]  netlink_rcv_skb+0xe7/0x120
[    31.375586]  netlink_unicast+0x1a8/0x250
[    31.375588]  netlink_sendmsg+0x2cb/0x3c0
[    31.375590]  sock_sendmsg+0x30/0x40
[    31.375592]  ___sys_sendmsg+0x2d7/0x2f0
[    31.375594]  ? __do_proc_dointvec+0x2ec/0x3f0
[    31.375596]  ? __rtnl_unlock+0x25/0x40
[    31.375597]  ? netdev_run_todo+0x61/0x310
[    31.375598]  ? ___cache_free+0x31/0x2e0
[    31.375600]  ? preempt_count_add+0x56/0xa0
[    31.375602]  ? _raw_spin_lock+0x13/0x40
[    31.375604]  ? lockref_put_or_lock+0x5a/0x80
[    31.375605]  ? dput+0x16e/0x200
[    31.375607]  ? __sys_sendmsg+0x51/0x90
[    31.375609]  __sys_sendmsg+0x51/0x90
[    31.375611]  system_call_fast_compare_end+0xc/0x6f
[    31.375613] RIP: 0033:0x7f6e7a67de90
[    31.375614] RSP: 002b:00007ffc44ad0b20 EFLAGS: 00000293
[    33.139621] iwlwifi 0000:03:00.0: Microcode SW error detected.  Restarting
0x82000000.
[    33.141713] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[    33.141719] iwlwifi 0000:03:00.0: Status: 0x00000110, count: 6
[    33.141723] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[    33.141727] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[    33.141730] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[    33.141733] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[    33.141736] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[    33.141739] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[    33.141742] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[    33.141745] iwlwifi 0000:03:00.0: 0x00000002 | data1
[    33.141748] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[    33.141751] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[    33.141754] iwlwifi 0000:03:00.0: 0x003FA661 | beacon time
[    33.141758] iwlwifi 0000:03:00.0: 0x0000599D | tsf low
[    33.141761] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[    33.141764] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[    33.141767] iwlwifi 0000:03:00.0: 0x0000599E | time gp2
[    33.141770] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[    33.141773] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[    33.141776] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[    33.141779] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[    33.141782] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[    33.141785] iwlwifi 0000:03:00.0: 0x001F0405 | hcmd
[    33.141788] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[    33.141795] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[    33.141797] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[    33.141800] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[    33.141803] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[    33.141806] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[    33.141809] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[    33.141812] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[    33.141815] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
```

[33.141817] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[33.141820] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[33.141823] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[33.141826] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[33.141829] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[33.142739] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[33.142742] iwlwifi 0000:03:00.0: Status: 0x00000110, count: 7
[33.142746] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[33.142748] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[33.142751] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[33.142754] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[33.142757] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[33.142760] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[33.142764] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[33.142767] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[33.142769] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[33.142775] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[33.142778] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[33.142781] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[33.142784] iwlwifi 0000:03:00.0: 0x001F0405 | last host cmd
[33.142787] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[33.142791] iwlwifi 0000:03:00.0: Firmware error during reconfiguration - reprobe!
[33.142856] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[33.142866] CPU: 6 PID: 677 Comm: wpa_supplicant Tainted: P W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[33.142868] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[33.142870] Call Trace:
[33.142882] dump_stack+0x5c/0x85
[33.142899] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[33.142907] ? remove_wait_queue+0x60/0x60
[33.142919] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[33.142934] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[33.142945] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[33.142956] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[33.142963] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[33.142971] ? iwl_mvm_channel_switch+0x10/0x10 [iwlmvm]
[33.142981] __iwl_mvm_mac_start+0x2b3/0x350 [iwlmvm]
[33.142991] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[33.142997] ? _raw_spin_unlock_irqrestore+0x20/0x40
[33.143028] drv_start+0x35/0x110 [mac80211]
[33.143057] ieee80211_do_open+0x302/0x8f0 [mac80211]
[33.143082] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[33.143089] __dev_open+0xc2/0x140
[33.143094] ? _raw_spin_lock_bh+0x13/0x40
[33.143099] __dev_change_flags+0x1a7/0x1e0
[33.143104] ? ___sys_recvmsg+0x188/0x230
[33.143109] dev_change_flags+0x23/0x60
[33.143114] devinet_ioctl+0x5f9/0x6b0
[33.143120] ? sock_do_ioctl+0x20/0x50
[33.143123] sock_do_ioctl+0x20/0x50
[33.143127] sock_ioctl+0x1ed/0x2b0

```
[    33.143132]   do_vfs_ioctl+0x9f/0x610
[    33.143137]   ? __sys_recvmsg+0x4e/0x90
[    33.143141]   ? __sys_recvmsg+0x4e/0x90
[    33.143145]   SyS_ioctl+0x74/0x80
[    33.143150]   system_call_fast_compare_end+0xc/0x6f
[    33.143154] RIP: 0033:0x7faa895b6d97
[    33.143157] RSP: 002b:00007ffd33717a38 EFLAGS: 00000246
[    33.357247] iwlwifi 0000:03:00.0: Microcode SW error detected.  Restarting 0x82000000.
[    33.359323] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[    33.359328] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 6
[    33.359331] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[    33.359335] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[    33.359339] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[    33.359342] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[    33.359345] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[    33.359348] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[    33.359351] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[    33.359354] iwlwifi 0000:03:00.0: 0x00000002 | data1
[    33.359357] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[    33.359359] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[    33.359362] iwlwifi 0000:03:00.0: 0x003FB26A | beacon time
[    33.359365] iwlwifi 0000:03:00.0: 0x00004D94 | tsf low
[    33.359368] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[    33.359371] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[    33.359374] iwlwifi 0000:03:00.0: 0x00004D95 | time gp2
[    33.359377] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[    33.359380] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[    33.359383] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[    33.359386] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[    33.359389] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[    33.359392] iwlwifi 0000:03:00.0: 0x001E0405 | hcmd
[    33.359395] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[    33.359397] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[    33.359400] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[    33.359403] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[    33.359406] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[    33.359409] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[    33.359412] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[    33.359415] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[    33.359418] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[    33.359421] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[    33.359423] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[    33.359426] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[    33.359429] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[    33.359432] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[    33.360376] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[    33.360379] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 7
[    33.360383] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[    33.360386] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[    33.360389] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[    33.360391] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[    33.360394] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
```

[33.360397] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[33.360400] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[33.360407] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[33.360410] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[33.360413] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[33.360416] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[33.360419] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[33.360422] iwlwifi 0000:03:00.0: 0x001E0405 | last host cmd
[33.360424] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[33.360431] ieee80211 phy8: Hardware restart was requested
[33.360449] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[33.360457] CPU: 3 PID: 677 Comm: wpa_supplicant Tainted: P W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[33.360459] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[33.360461] Call Trace:
[33.360474] dump_stack+0x5c/0x85
[33.360492] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[33.360500] ? remove_wait_queue+0x60/0x60
[33.360514] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[33.360529] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[33.360541] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[33.360553] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[33.360562] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[33.360569] ? preempt_count_add+0x56/0xa0
[33.360585] __iwl_mvm_mac_start+0x2d5/0x350 [iwlmvm]
[33.360597] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[33.360602] ? chrdev_open+0xaf/0x1f0
[33.360632] drv_start+0x35/0x110 [mac80211]
[33.360659] ieee80211_do_open+0x302/0x8f0 [mac80211]
[33.360683] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[33.360690] __dev_open+0xc2/0x140
[33.360695] ? _raw_spin_lock_bh+0x13/0x40
[33.360700] __dev_change_flags+0x1a7/0x1e0
[33.360706] dev_change_flags+0x23/0x60
[33.360710] devinet_ioctl+0x5f9/0x6b0
[33.360715] ? ___cache_free+0x31/0x2e0
[33.360721] ? sock_do_ioctl+0x20/0x50
[33.360724] sock_do_ioctl+0x20/0x50
[33.360728] sock_ioctl+0x1ed/0x2b0
[33.360732] do_vfs_ioctl+0x9f/0x610
[33.360737] ? vfs_read+0x91/0x130
[33.360741] SyS_ioctl+0x74/0x80
[33.360746] system_call_fast_compare_end+0xc/0x6f
[33.360750] RIP: 0033:0x7faa895b6d97
[33.360753] RSP: 002b:00007ffd337178c8 EFLAGS: 00000246
[33.499512] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-34.ucode (-2)
[33.499517] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-34.ucode failed with error -2
[33.499527] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-33.ucode (-2)
[33.499529] iwlwifi 0000:03:00.0: Direct firmware load for

iwlwifi-8265-33.ucode failed with error -2
[33.499537] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-32.ucode (-2)
[33.499539] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-32.ucode failed with error -2
[33.499547] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-31.ucode (-2)
[33.499549] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-31.ucode failed with error -2
[33.499556] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-30.ucode (-2)
[33.499558] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-30.ucode failed with error -2
[33.499565] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-29.ucode (-2)
[33.499567] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-29.ucode failed with error -2
[33.499574] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-28.ucode (-2)
[33.499576] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-28.ucode failed with error -2
[33.499583] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-27.ucode (-2)
[33.499585] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-27.ucode failed with error -2
[33.499592] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-26.ucode (-2)
[33.499594] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-26.ucode failed with error -2
[33.499601] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-25.ucode (-2)
[33.499603] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-25.ucode failed with error -2
[33.499610] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-24.ucode (-2)
[33.499612] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-24.ucode failed with error -2
[33.499619] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-23.ucode (-2)
[33.499621] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-23.ucode failed with error -2
[33.500159] iwlwifi 0000:03:00.0: firmware: direct-loading firmware iwlwifi-8265-22.ucode
[33.500817] iwlwifi 0000:03:00.0: loaded firmware version 22.361476.0 op_mode iwlmvm
[33.500830] iwlwifi 0000:03:00.0: Detected Intel(R) Dual Band Wireless AC 8265, REV=0x230
[33.558110] iwlwifi 0000:03:00.0: base HW address: f8:34:41:07:39:a1
[33.634601] ieee80211 phy9: Selected rate control algorithm 'iwl-mvm-rs'
[33.634963] (NULL device *): hwmon_device_register() is deprecated. Please convert the driver to use hwmon_device_register_with_info().
[33.634989] thermal thermal_zone12: failed to read out thermal zone (-61)
[33.640516] iwlwifi 0000:03:00.0 wlp3s0: renamed from wlan0

```
[    33.672377] IPv6: ADDRCONF(NETDEV_UP): wlp3s0: link is not ready
[    33.867637] iwlwifi 0000:03:00.0: Microcode SW error detected.  Restarting 0x82000000.
[    33.869086] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[    33.869089] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 6
[    33.869091] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[    33.869093] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[    33.869094] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[    33.869096] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[    33.869098] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[    33.869100] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[    33.869101] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[    33.869103] iwlwifi 0000:03:00.0: 0x00000002 | data1
[    33.869104] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[    33.869106] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[    33.869108] iwlwifi 0000:03:00.0: 0x003FC444 | beacon time
[    33.869109] iwlwifi 0000:03:00.0: 0x00003BBA | tsf low
[    33.869111] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[    33.869113] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[    33.869114] iwlwifi 0000:03:00.0: 0x00003BBB | time gp2
[    33.869116] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[    33.869118] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[    33.869119] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[    33.869121] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[    33.869123] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[    33.869124] iwlwifi 0000:03:00.0: 0x00200405 | hcmd
[    33.869126] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[    33.869128] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[    33.869129] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[    33.869131] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[    33.869132] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[    33.869135] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[    33.869137] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[    33.869139] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[    33.869140] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[    33.869142] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[    33.869144] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[    33.869145] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[    33.869147] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[    33.869149] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[    33.870011] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[    33.870013] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 7
[    33.870015] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[    33.870017] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[    33.870019] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[    33.870021] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[    33.870022] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[    33.870024] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[    33.870026] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[    33.870027] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[    33.870029] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[    33.870030] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[    33.870032] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
```

[33.870034] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[33.870035] iwlwifi 0000:03:00.0: 0x00200405 | last host cmd
[33.870037] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[33.870040] ieee80211 phy9: Hardware restart was requested
[33.870084] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[33.870087] CPU: 6 PID: 612 Comm: NetworkManager Tainted: P W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[33.870088] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[33.870089] Call Trace:
[33.870095] dump_stack+0x5c/0x85
[33.870102] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[33.870105] ? remove_wait_queue+0x60/0x60
[33.870109] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[33.870115] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[33.870119] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[33.870123] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[33.870125] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[33.870128] ? preempt_count_add+0x56/0xa0
[33.870131] __iwl_mvm_mac_start+0x2d5/0x350 [iwlmvm]
[33.870135] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[33.870153] drv_start+0x35/0x110 [mac80211]
[33.870163] ieee80211_do_open+0x302/0x8f0 [mac80211]
[33.870172] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[33.870175] __dev_open+0xc2/0x140
[33.870177] ? _raw_spin_lock_bh+0x13/0x40
[33.870179] __dev_change_flags+0x1a7/0x1e0
[33.870181] dev_change_flags+0x23/0x60
[33.870184] do_setlink+0x324/0xcc0
[33.870186] ? __kmalloc_reserve.isra.37+0x2e/0x80
[33.870188] ? pskb_expand_head+0xe1/0x2b0
[33.870190] ? ___cache_free+0x31/0x2e0
[33.870191] ? __local_bh_enable_ip+0x3f/0x70
[33.870193] ? inet6_fill_ifla6_attrs+0x451/0x470
[33.870195] rtnl_newlink+0x7f6/0x920
[33.870197] ? sock_def_readable+0xe/0x70
[33.870199] ? __netlink_sendskb+0x47/0x60
[33.870203] ? ttwu_stat+0x110/0x120
[33.870204] ? _raw_write_unlock_bh+0x20/0x20
[33.870206] ? security_capable+0x41/0x60
[33.870208] rtnetlink_rcv_msg+0x17e/0x2b0
[33.870210] ? rtnl_calcit.isra.26+0x120/0x120
[33.870212] netlink_rcv_skb+0xe7/0x120
[33.870214] netlink_unicast+0x1a8/0x250
[33.870216] netlink_sendmsg+0x2cb/0x3c0
[33.870218] sock_sendmsg+0x30/0x40
[33.870220] ___sys_sendmsg+0x2d7/0x2f0
[33.870222] ? __do_proc_dointvec+0x2ec/0x3f0
[33.870224] ? __rtnl_unlock+0x25/0x40
[33.870225] ? netdev_run_todo+0x61/0x310
[33.870226] ? ___cache_free+0x31/0x2e0
[33.870228] ? preempt_count_add+0x56/0xa0
[33.870230] ? _raw_spin_lock+0x13/0x40

```
[    33.870232]   ? lockref_put_or_lock+0x5a/0x80
[    33.870234]   ? dput+0x16e/0x200
[    33.870235]   ? __sys_sendmsg+0x51/0x90
[    33.870237]   __sys_sendmsg+0x51/0x90
[    33.870239]   system_call_fast_compare_end+0xc/0x6f
[    33.870241] RIP: 0033:0x7f6e7a67de90
[    33.870242] RSP: 002b:00007ffc44ad0b20 EFLAGS: 00000293
[    35.629231] iwlwifi 0000:03:00.0: Microcode SW error detected.  Restarting 0x82000000.
[    35.629405] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[    35.629410] iwlwifi 0000:03:00.0: Status: 0x00000110, count: 6
[    35.629414] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[    35.629418] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[    35.629422] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[    35.629426] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[    35.629429] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[    35.629432] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[    35.629436] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[    35.629439] iwlwifi 0000:03:00.0: 0x00000002 | data1
[    35.629442] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[    35.629445] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[    35.629449] iwlwifi 0000:03:00.0: 0x003FAB7D | beacon time
[    35.629452] iwlwifi 0000:03:00.0: 0x00005482 | tsf low
[    35.629455] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[    35.629458] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[    35.629462] iwlwifi 0000:03:00.0: 0x00005483 | time gp2
[    35.629465] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[    35.629468] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[    35.629472] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[    35.629475] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[    35.629478] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[    35.629481] iwlwifi 0000:03:00.0: 0x001F0405 | hcmd
[    35.629485] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[    35.629488] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[    35.629491] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[    35.629494] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[    35.629497] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[    35.629500] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[    35.629503] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[    35.629507] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[    35.629510] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[    35.629513] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[    35.629516] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[    35.629520] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[    35.629523] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[    35.629526] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[    35.629694] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[    35.629697] iwlwifi 0000:03:00.0: Status: 0x00000110, count: 7
[    35.629701] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[    35.629704] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[    35.629707] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[    35.629711] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[    35.629714] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
```

[35.629717] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[35.629720] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[35.629723] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[35.629727] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[35.629730] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[35.629733] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[35.629736] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[35.629739] iwlwifi 0000:03:00.0: 0x001F0405 | last host cmd
[35.629743] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[35.629747] iwlwifi 0000:03:00.0: Firmware error during reconfiguration - reprobe!
[35.629776] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[35.629787] CPU: 6 PID: 677 Comm: wpa_supplicant Tainted: P W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[35.629789] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[35.629791] Call Trace:
[35.629805] dump_stack+0x5c/0x85
[35.629822] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[35.629830] ? remove_wait_queue+0x60/0x60
[35.629844] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[35.629859] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[35.629871] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[35.629882] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[35.629890] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[35.629899] ? iwl_mvm_channel_switch+0x10/0x10 [iwlmvm]
[35.629910] __iwl_mvm_mac_start+0x2b3/0x350 [iwlmvm]
[35.629921] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[35.629927] ? _raw_spin_unlock_irqrestore+0x20/0x40
[35.629959] drv_start+0x35/0x110 [mac80211]
[35.629988] ieee80211_do_open+0x302/0x8f0 [mac80211]
[35.630014] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[35.630021] __dev_open+0xc2/0x140
[35.630026] ? _raw_spin_lock_bh+0x13/0x40
[35.630032] __dev_change_flags+0x1a7/0x1e0
[35.630037] ? ___sys_recvmsg+0x188/0x230
[35.630043] dev_change_flags+0x23/0x60
[35.630048] devinet_ioctl+0x5f9/0x6b0
[35.630055] ? sock_do_ioctl+0x20/0x50
[35.630059] sock_do_ioctl+0x20/0x50
[35.630063] sock_ioctl+0x1ed/0x2b0
[35.630068] do_vfs_ioctl+0x9f/0x610
[35.630074] ? __sys_recvmsg+0x4e/0x90
[35.630078] ? __sys_recvmsg+0x4e/0x90
[35.630082] SyS_ioctl+0x74/0x80
[35.630088] system_call_fast_compare_end+0xc/0x6f
[35.630093] RIP: 0033:0x7faa895b6d97
[35.630095] RSP: 002b:00007ffd33717a38 EFLAGS: 00000246
[35.846594] iwlwifi 0000:03:00.0: Microcode SW error detected. Restarting 0x82000000.
[35.846807] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[35.846812] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 6
[35.846816] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0

```
[    35.846821] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[    35.846825] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[    35.846828] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[    35.846831] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[    35.846835] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[    35.846838] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[    35.846841] iwlwifi 0000:03:00.0: 0x00000002 | data1
[    35.846844] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[    35.846848] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[    35.846851] iwlwifi 0000:03:00.0: 0x003FA836 | beacon time
[    35.846854] iwlwifi 0000:03:00.0: 0x000057C8 | tsf low
[    35.846857] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[    35.846860] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[    35.846864] iwlwifi 0000:03:00.0: 0x000057C9 | time gp2
[    35.846867] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[    35.846870] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[    35.846874] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[    35.846877] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[    35.846881] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[    35.846884] iwlwifi 0000:03:00.0: 0x001E0405 | hcmd
[    35.846887] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[    35.846890] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[    35.846893] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[    35.846896] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[    35.846899] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[    35.846903] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[    35.846906] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[    35.846909] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[    35.846912] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[    35.846915] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[    35.846919] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[    35.846922] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[    35.846925] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[    35.846928] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[    35.847097] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[    35.847100] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 7
[    35.847104] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[    35.847107] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[    35.847111] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[    35.847114] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[    35.847117] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[    35.847120] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[    35.847123] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[    35.847126] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[    35.847129] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[    35.847132] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[    35.847135] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[    35.847139] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[    35.847142] iwlwifi 0000:03:00.0: 0x001E0405 | last host cmd
[    35.847145] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[    35.847153] ieee80211 phy9: Hardware restart was requested
[    35.847264] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[    35.847275] CPU: 6 PID: 677 Comm: wpa_supplicant Tainted: P           W    O
```

4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[35.847278] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[35.847279] Call Trace:
[35.847293] dump_stack+0x5c/0x85
[35.847313] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[35.847322] ? remove_wait_queue+0x60/0x60
[35.847335] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[35.847352] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[35.847364] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[35.847375] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[35.847382] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[35.847390] ? preempt_count_add+0x56/0xa0
[35.847401] __iwl_mvm_mac_start+0x2d5/0x350 [iwlmvm]
[35.847411] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[35.847416] ? chrdev_open+0xaf/0x1f0
[35.847452] drv_start+0x35/0x110 [mac80211]
[35.847485] ieee80211_do_open+0x302/0x8f0 [mac80211]
[35.847514] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[35.847523] __dev_open+0xc2/0x140
[35.847529] ? _raw_spin_lock_bh+0x13/0x40
[35.847538] __dev_change_flags+0x1a7/0x1e0
[35.847544] dev_change_flags+0x23/0x60
[35.847549] devinet_ioctl+0x5f9/0x6b0
[35.847555] ? ___cache_free+0x31/0x2e0
[35.847562] ? sock_do_ioctl+0x20/0x50
[35.847566] sock_do_ioctl+0x20/0x50
[35.847570] sock_ioctl+0x1ed/0x2b0
[35.847575] do_vfs_ioctl+0x9f/0x610
[35.847581] ? vfs_read+0x91/0x130
[35.847585] SyS_ioctl+0x74/0x80
[35.847592] system_call_fast_compare_end+0xc/0x6f
[35.847596] RIP: 0033:0x7faa895b6d97
[35.847599] RSP: 002b:00007ffd337178c8 EFLAGS: 00000246
[35.970234] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-34.ucode (-2)
[35.970239] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-34.ucode failed with error -2
[35.970249] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-33.ucode (-2)
[35.970251] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-33.ucode failed with error -2
[35.970258] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-32.ucode (-2)
[35.970260] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-32.ucode failed with error -2
[35.970267] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-31.ucode (-2)
[35.970269] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-31.ucode failed with error -2
[35.970276] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-30.ucode (-2)
[35.970278] iwlwifi 0000:03:00.0: Direct firmware load for

iwlwifi-8265-30.ucode failed with error -2
[35.970285] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-29.ucode (-2)
[35.970287] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-29.ucode failed with error -2
[35.970295] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-28.ucode (-2)
[35.970296] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-28.ucode failed with error -2
[35.970303] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-27.ucode (-2)
[35.970305] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-27.ucode failed with error -2
[35.970313] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-26.ucode (-2)
[35.970314] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-26.ucode failed with error -2
[35.970322] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-25.ucode (-2)
[35.970323] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-25.ucode failed with error -2
[35.970331] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-24.ucode (-2)
[35.970332] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-24.ucode failed with error -2
[35.970340] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-23.ucode (-2)
[35.970342] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-23.ucode failed with error -2
[35.970875] iwlwifi 0000:03:00.0: firmware: direct-loading firmware iwlwifi-8265-22.ucode
[35.971444] iwlwifi 0000:03:00.0: loaded firmware version 22.361476.0 op_mode iwlmvm
[35.971457] iwlwifi 0000:03:00.0: Detected Intel(R) Dual Band Wireless AC 8265, REV=0x230
[36.029967] iwlwifi 0000:03:00.0: base HW address: f8:34:41:07:39:a1
[36.114797] ieee80211 phy10: Selected rate control algorithm 'iwl-mvm-rs'
[36.117626] (NULL device *): hwmon_device_register() is deprecated. Please convert the driver to use hwmon_device_register_with_info().
[36.117682] thermal thermal_zone12: failed to read out thermal zone (-61)
[36.121942] iwlwifi 0000:03:00.0 wlp3s0: renamed from wlan0
[36.165457] IPv6: ADDRCONF(NETDEV_UP): wlp3s0: link is not ready
[36.360513] iwlwifi 0000:03:00.0: Microcode SW error detected. Restarting 0x2000000.
[36.360689] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[36.360690] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 6
[36.360691] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[36.360695] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[36.360696] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[36.360697] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[36.360697] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[36.360698] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[36.360699] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2

[36.360700] iwlwifi 0000:03:00.0: 0x00000002 | data1
[36.360701] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[36.360702] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[36.360703] iwlwifi 0000:03:00.0: 0x003FBEB7 | beacon time
[36.360704] iwlwifi 0000:03:00.0: 0x00004147 | tsf low
[36.360705] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[36.360706] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[36.360707] iwlwifi 0000:03:00.0: 0x00004148 | time gp2
[36.360709] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[36.360710] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[36.360711] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[36.360712] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[36.360713] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[36.360714] iwlwifi 0000:03:00.0: 0x00200405 | hcmd
[36.360714] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[36.360715] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[36.360716] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[36.360717] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[36.360718] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[36.360719] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[36.360720] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[36.360720] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[36.360721] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[36.360722] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[36.360723] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[36.360724] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[36.360725] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[36.360726] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[36.360888] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[36.360889] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 7
[36.360890] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[36.360891] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[36.360892] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[36.360893] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[36.360894] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[36.360895] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[36.360895] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[36.360896] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[36.360897] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[36.360898] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[36.360899] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[36.360900] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[36.360900] iwlwifi 0000:03:00.0: 0x00200405 | last host cmd
[36.360901] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[36.360903] ieee80211 phy10: Hardware restart was requested
[36.360909] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[36.360913] CPU: 7 PID: 612 Comm: NetworkManager Tainted: P   W O
4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[36.360913] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver.
01.02.09 01/26/2018
[36.360914] Call Trace:
[36.360919] dump_stack+0x5c/0x85
[36.360925] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]

[36.360928] ? remove_wait_queue+0x60/0x60
[36.360932] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[36.360937] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[36.360941] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[36.360944] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[36.360946] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[36.360948] ? preempt_count_add+0x56/0xa0
[36.360951] __iwl_mvm_mac_start+0x2d5/0x350 [iwlmvm]
[36.360954] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[36.360971] drv_start+0x35/0x110 [mac80211]
[36.360979] ieee80211_do_open+0x302/0x8f0 [mac80211]
[36.360987] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[36.360990] __dev_open+0xc2/0x140
[36.360991] ? _raw_spin_lock_bh+0x13/0x40
[36.360993] __dev_change_flags+0x1a7/0x1e0
[36.360995] dev_change_flags+0x23/0x60
[36.360997] do_setlink+0x324/0xcc0
[36.361000] ? __kmalloc_reserve.isra.37+0x2e/0x80
[36.361001] ? pskb_expand_head+0xe1/0x2b0
[36.361002] ? ___cache_free+0x31/0x2e0
[36.361004] ? __local_bh_enable_ip+0x3f/0x70
[36.361005] ? inet6_fill_ifla6_attrs+0x451/0x470
[36.361007] rtnl_newlink+0x7f6/0x920
[36.361009] ? sock_def_readable+0xe/0x70
[36.361010] ? __netlink_sendskb+0x47/0x60
[36.361014] ? ttwu_stat+0x110/0x120
[36.361015] ? _raw_write_unlock_bh+0x20/0x20
[36.361016] ? security_capable+0x41/0x60
[36.361018] rtnetlink_rcv_msg+0x17e/0x2b0
[36.361020] ? rtnl_calcit.isra.26+0x120/0x120
[36.361021] netlink_rcv_skb+0xe7/0x120
[36.361023] netlink_unicast+0x1a8/0x250
[36.361025] netlink_sendmsg+0x2cb/0x3c0
[36.361027] sock_sendmsg+0x30/0x40
[36.361028] ___sys_sendmsg+0x2d7/0x2f0
[36.361030] ? __do_proc_dointvec+0x2ec/0x3f0
[36.361031] ? __rtnl_unlock+0x25/0x40
[36.361032] ? netdev_run_todo+0x61/0x310
[36.361033] ? ___cache_free+0x31/0x2e0
[36.361035] ? preempt_count_add+0x56/0xa0
[36.361036] ? _raw_spin_lock+0x13/0x40
[36.361038] ? lockref_put_or_lock+0x5a/0x80
[36.361040] ? dput+0x16e/0x200
[36.361041] ? __sys_sendmsg+0x51/0x90
[36.361042] __sys_sendmsg+0x51/0x90
[36.361044] system_call_fast_compare_end+0xc/0x6f
[36.361046] RIP: 0033:0x7f6e7a67de90
[36.361047] RSP: 002b:00007ffc44ad0b20 EFLAGS: 00000293
[38.117231] iwlwifi 0000:03:00.0: Microcode SW error detected. Restarting 0x82000000.
[38.117398] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[38.117402] iwlwifi 0000:03:00.0: Status: 0x00000110, count: 6
[38.117405] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0

[38.117409] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[38.117412] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[38.117414] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[38.117417] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[38.117419] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[38.117422] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[38.117424] iwlwifi 0000:03:00.0: 0x00000002 | data1
[38.117427] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[38.117429] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[38.117431] iwlwifi 0000:03:00.0: 0x003FBF39 | beacon time
[38.117434] iwlwifi 0000:03:00.0: 0x000040C5 | tsf low
[38.117436] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[38.117439] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[38.117441] iwlwifi 0000:03:00.0: 0x000040C6 | time gp2
[38.117444] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[38.117446] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[38.117449] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[38.117451] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[38.117454] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[38.117456] iwlwifi 0000:03:00.0: 0x001F0405 | hcmd
[38.117458] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[38.117461] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[38.117463] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[38.117465] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[38.117468] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[38.117470] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[38.117473] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[38.117475] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[38.117477] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[38.117480] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[38.117482] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[38.117485] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[38.117487] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[38.117489] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[38.117657] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[38.117661] iwlwifi 0000:03:00.0: Status: 0x00000110, count: 7
[38.117666] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[38.117670] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[38.117673] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[38.117677] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[38.117680] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[38.117684] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[38.117688] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[38.117693] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[38.117697] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[38.117701] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[38.117706] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[38.117710] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[38.117714] iwlwifi 0000:03:00.0: 0x001F0405 | last host cmd
[38.117718] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[38.117724] iwlwifi 0000:03:00.0: Firmware error during reconfiguration - reprobe!
[38.117744] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT

[38.117752] CPU: 4 PID: 677 Comm: wpa_supplicant Tainted: P W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[38.117754] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[38.117756] Call Trace:
[38.117766] dump_stack+0x5c/0x85
[38.117779] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[38.117786] ? remove_wait_queue+0x60/0x60
[38.117797] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[38.117812] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[38.117823] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[38.117836] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[38.117845] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[38.117854] ? iwl_mvm_channel_switch+0x10/0x10 [iwlmvm]
[38.117866] __iwl_mvm_mac_start+0x2b3/0x350 [iwlmvm]
[38.117878] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[38.117884] ? _raw_spin_unlock_irqrestore+0x20/0x40
[38.117914] drv_start+0x35/0x110 [mac80211]
[38.117947] ieee80211_do_open+0x302/0x8f0 [mac80211]
[38.117976] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[38.117983] __dev_open+0xc2/0x140
[38.117988] ? _raw_spin_lock_bh+0x13/0x40
[38.117994] __dev_change_flags+0x1a7/0x1e0
[38.117999] ? ___sys_recvmsg+0x188/0x230
[38.118005] dev_change_flags+0x23/0x60
[38.118009] devinet_ioctl+0x5f9/0x6b0
[38.118017] ? sock_do_ioctl+0x20/0x50
[38.118019] sock_do_ioctl+0x20/0x50
[38.118024] sock_ioctl+0x1ed/0x2b0
[38.118028] do_vfs_ioctl+0x9f/0x610
[38.118034] ? __sys_recvmsg+0x4e/0x90
[38.118038] ? __sys_recvmsg+0x4e/0x90
[38.118043] SyS_ioctl+0x74/0x80
[38.118049] system_call_fast_compare_end+0xc/0x6f
[38.118053] RIP: 0033:0x7faa895b6d97
[38.118056] RSP: 002b:00007ffd33717a38 EFLAGS: 00000246
[38.336893] iwlwifi 0000:03:00.0: Microcode SW error detected. Restarting 0x82000000.
[38.337057] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[38.337062] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 6
[38.337065] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[38.337070] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[38.337074] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[38.337077] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[38.337081] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[38.337084] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[38.337087] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[38.337090] iwlwifi 0000:03:00.0: 0x00000002 | data1
[38.337094] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[38.337097] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[38.337100] iwlwifi 0000:03:00.0: 0x003F9684 | beacon time
[38.337103] iwlwifi 0000:03:00.0: 0x0000697B | tsf low
[38.337107] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi

[38.337110] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[38.337113] iwlwifi 0000:03:00.0: 0x0000697B | time gp2
[38.337116] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[38.337120] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[38.337123] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[38.337126] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[38.337129] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[38.337132] iwlwifi 0000:03:00.0: 0x001E0405 | hcmd
[38.337136] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[38.337139] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[38.337142] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[38.337145] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[38.337148] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[38.337151] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[38.337155] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[38.337158] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[38.337161] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[38.337164] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[38.337167] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[38.337171] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[38.337174] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[38.337177] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[38.337345] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[38.337349] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 7
[38.337352] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[38.337356] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[38.337359] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[38.337362] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[38.337365] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[38.337368] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[38.337371] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[38.337375] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[38.337378] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[38.337381] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[38.337384] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[38.337388] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[38.337391] iwlwifi 0000:03:00.0: 0x001E0405 | last host cmd
[38.337394] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[38.337401] ieee80211 phy10: Hardware restart was requested
[38.337472] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[38.337484] CPU: 7 PID: 677 Comm: wpa_supplicant Tainted: P   W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[38.337486] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[38.337488] Call Trace:
[38.337501] dump_stack+0x5c/0x85
[38.337520] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[38.337528] ? remove_wait_queue+0x60/0x60
[38.337542] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[38.337558] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[38.337571] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[38.337582] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[38.337590] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]

[38.337597] ? preempt_count_add+0x56/0xa0
[38.337608] __iwl_mvm_mac_start+0x2d5/0x350 [iwlmvm]
[38.337619] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[38.337624] ? chrdev_open+0xaf/0x1f0
[38.337657] drv_start+0x35/0x110 [mac80211]
[38.337688] ieee80211_do_open+0x302/0x8f0 [mac80211]
[38.337716] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[38.337724] __dev_open+0xc2/0x140
[38.337730] ? _raw_spin_lock_bh+0x13/0x40
[38.337735] __dev_change_flags+0x1a7/0x1e0
[38.337742] dev_change_flags+0x23/0x60
[38.337746] devinet_ioctl+0x5f9/0x6b0
[38.337752] ? ___cache_free+0x31/0x2e0
[38.337758] ? sock_do_ioctl+0x20/0x50
[38.337762] sock_do_ioctl+0x20/0x50
[38.337766] sock_ioctl+0x1ed/0x2b0
[38.337770] do_vfs_ioctl+0x9f/0x610
[38.337776] ? vfs_read+0x91/0x130
[38.337780] SyS_ioctl+0x74/0x80
[38.337785] system_call_fast_compare_end+0xc/0x6f
[38.337790] RIP: 0033:0x7faa895b6d97
[38.337792] RSP: 002b:00007ffd337178c8 EFLAGS: 00000246
[38.466580] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-34.ucode (-2)
[38.466584] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-34.ucode failed with error -2
[38.466593] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-33.ucode (-2)
[38.466595] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-33.ucode failed with error -2
[38.466601] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-32.ucode (-2)
[38.466602] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-32.ucode failed with error -2
[38.466609] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-31.ucode (-2)
[38.466610] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-31.ucode failed with error -2
[38.466616] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-30.ucode (-2)
[38.466618] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-30.ucode failed with error -2
[38.466624] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-29.ucode (-2)
[38.466625] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-29.ucode failed with error -2
[38.466631] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-28.ucode (-2)
[38.466633] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-28.ucode failed with error -2
[38.466639] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-27.ucode (-2)
[38.466641] iwlwifi 0000:03:00.0: Direct firmware load for

iwlwifi-8265-27.ucode failed with error -2
[38.466647] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-26.ucode (-2)
[38.466648] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-26.ucode failed with error -2
[38.466654] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-25.ucode (-2)
[38.466656] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-25.ucode failed with error -2
[38.466662] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-24.ucode (-2)
[38.466663] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-24.ucode failed with error -2
[38.466670] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-23.ucode (-2)
[38.466671] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-23.ucode failed with error -2
[38.467261] iwlwifi 0000:03:00.0: firmware: direct-loading firmware iwlwifi-8265-22.ucode
[38.467836] iwlwifi 0000:03:00.0: loaded firmware version 22.361476.0 op_mode iwlmvm
[38.467849] iwlwifi 0000:03:00.0: Detected Intel(R) Dual Band Wireless AC 8265, REV=0x230
[38.524666] iwlwifi 0000:03:00.0: base HW address: f8:34:41:07:39:a1
[38.600260] ieee80211 phy11: Selected rate control algorithm 'iwl-mvm-rs'
[38.600506] (NULL device *): hwmon_device_register() is deprecated. Please convert the driver to use hwmon_device_register_with_info().
[38.600520] thermal thermal_zone12: failed to read out thermal zone (-61)
[38.602568] iwlwifi 0000:03:00.0 wlp3s0: renamed from wlan0
[38.644216] IPv6: ADDRCONF(NETDEV_UP): wlp3s0: link is not ready
[38.844828] iwlwifi 0000:03:00.0: Microcode SW error detected. Restarting 0x82000000.
[38.845014] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[38.845016] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 6
[38.845018] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[38.845020] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[38.845021] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[38.845023] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[38.845025] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[38.845027] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[38.845029] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[38.845030] iwlwifi 0000:03:00.0: 0x00000002 | data1
[38.845032] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[38.845033] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[38.845034] iwlwifi 0000:03:00.0: 0x003FC817 | beacon time
[38.845036] iwlwifi 0000:03:00.0: 0x000037E8 | tsf low
[38.845037] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[38.845038] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[38.845039] iwlwifi 0000:03:00.0: 0x000037E9 | time gp2
[38.845041] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[38.845042] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[38.845044] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[38.845045] iwlwifi 0000:03:00.0: 0x00000230 | hw version

[38.845046] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[38.845047] iwlwifi 0000:03:00.0: 0x00200405 | hcmd
[38.845049] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[38.845050] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[38.845051] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[38.845053] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[38.845054] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[38.845055] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[38.845056] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[38.845058] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[38.845059] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[38.845061] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[38.845062] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[38.845063] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[38.845064] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[38.845065] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[38.845371] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[38.845372] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 7
[38.845373] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[38.845374] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[38.845376] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[38.845377] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[38.845378] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[38.845379] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[38.845380] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[38.845381] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[38.845382] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[38.845383] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[38.845384] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[38.845386] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[38.845387] iwlwifi 0000:03:00.0: 0x00200405 | last host cmd
[38.845388] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[38.845390] ieee80211 phy11: Hardware restart was requested
[38.845438] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[38.845442] CPU: 5 PID: 612 Comm: NetworkManager Tainted: P   W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[38.845442] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[38.845443] Call Trace:
[38.845448] dump_stack+0x5c/0x85
[38.845455] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[38.845458] ? remove_wait_queue+0x60/0x60
[38.845462] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[38.845468] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[38.845472] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[38.845476] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[38.845478] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[38.845481] ? preempt_count_add+0x56/0xa0
[38.845485] __iwl_mvm_mac_start+0x2d5/0x350 [iwlmvm]
[38.845489] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[38.845501] drv_start+0x35/0x110 [mac80211]
[38.845512] ieee80211_do_open+0x302/0x8f0 [mac80211]
[38.845521] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]

```
[    38.845524]  __dev_open+0xc2/0x140
[    38.845526]  ? _raw_spin_lock_bh+0x13/0x40
[    38.845528]  __dev_change_flags+0x1a7/0x1e0
[    38.845531]  dev_change_flags+0x23/0x60
[    38.845533]  do_setlink+0x324/0xcc0
[    38.845535]  ? __kmalloc_reserve.isra.37+0x2e/0x80
[    38.845537]  ? pskb_expand_head+0xe1/0x2b0
[    38.845538]  ? ___cache_free+0x31/0x2e0
[    38.845540]  ? __local_bh_enable_ip+0x3f/0x70
[    38.845542]  ? inet6_fill_ifla6_attrs+0x451/0x470
[    38.845544]  rtnl_newlink+0x7f6/0x920
[    38.845546]  ? sock_def_readable+0xe/0x70
[    38.845548]  ? __netlink_sendskb+0x47/0x60
[    38.845552]  ? ttwu_stat+0x110/0x120
[    38.845554]  ? _raw_write_unlock_bh+0x20/0x20
[    38.845555]  ? security_capable+0x41/0x60
[    38.845557]  rtnetlink_rcv_msg+0x17e/0x2b0
[    38.845560]  ? rtnl_calcit.isra.26+0x120/0x120
[    38.845562]  netlink_rcv_skb+0xe7/0x120
[    38.845564]  netlink_unicast+0x1a8/0x250
[    38.845566]  netlink_sendmsg+0x2cb/0x3c0
[    38.845568]  sock_sendmsg+0x30/0x40
[    38.845570]  ___sys_sendmsg+0x2d7/0x2f0
[    38.845572]  ? __do_proc_dointvec+0x2ec/0x3f0
[    38.845574]  ? __rtnl_unlock+0x25/0x40
[    38.845575]  ? netdev_run_todo+0x61/0x310
[    38.845577]  ? ___cache_free+0x31/0x2e0
[    38.845579]  ? preempt_count_add+0x56/0xa0
[    38.845581]  ? _raw_spin_lock+0x13/0x40
[    38.845583]  ? lockref_put_or_lock+0x5a/0x80
[    38.845584]  ? dput+0x16e/0x200
[    38.845586]  ? __sys_sendmsg+0x51/0x90
[    38.845588]  __sys_sendmsg+0x51/0x90
[    38.845590]  system_call_fast_compare_end+0xc/0x6f
[    38.845592] RIP: 0033:0x7f6e7a67de90
[    38.845593] RSP: 002b:00007ffc44ad0b20 EFLAGS: 00000293
[    40.599060] iwlwifi 0000:03:00.0: Microcode SW error detected.  Restarting
0x82000000.
[    40.599234] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[    40.599239] iwlwifi 0000:03:00.0: Status: 0x00000110, count: 6
[    40.599243] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[    40.599248] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[    40.599251] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[    40.599255] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[    40.599258] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[    40.599261] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[    40.599265] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[    40.599268] iwlwifi 0000:03:00.0: 0x00000002 | data1
[    40.599271] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[    40.599274] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[    40.599277] iwlwifi 0000:03:00.0: 0x003FB138 | beacon time
[    40.599281] iwlwifi 0000:03:00.0: 0x00004EC6 | tsf low
[    40.599284] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
```

[40.599287] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[40.599290] iwlwifi 0000:03:00.0: 0x00004EC8 | time gp2
[40.599293] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[40.599297] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[40.599300] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[40.599303] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[40.599307] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[40.599310] iwlwifi 0000:03:00.0: 0x001F0405 | hcmd
[40.599313] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[40.599316] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[40.599320] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[40.599323] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[40.599326] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[40.599329] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[40.599332] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[40.599335] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[40.599339] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[40.599342] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[40.599345] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[40.599348] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[40.599351] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[40.599354] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[40.599523] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[40.599526] iwlwifi 0000:03:00.0: Status: 0x00000110, count: 7
[40.599530] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[40.599533] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[40.599536] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[40.599540] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[40.599543] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[40.599546] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[40.599549] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[40.599552] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[40.599555] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[40.599559] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[40.599562] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[40.599565] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[40.599568] iwlwifi 0000:03:00.0: 0x001F0405 | last host cmd
[40.599571] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[40.599576] iwlwifi 0000:03:00.0: Firmware error during reconfiguration - reprobe!
[40.599605] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[40.599617] CPU: 5 PID: 677 Comm: wpa_supplicant Tainted: P W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[40.599619] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[40.599621] Call Trace:
[40.599634] dump_stack+0x5c/0x85
[40.599652] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[40.599660] ? remove_wait_queue+0x60/0x60
[40.599673] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[40.599689] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[40.599701] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[40.599712] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]

[40.599720] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[40.599729] ? iwl_mvm_channel_switch+0x10/0x10 [iwlmvm]
[40.599740] __iwl_mvm_mac_start+0x2b3/0x350 [iwlmvm]
[40.599750] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[40.599756] ? _raw_spin_unlock_irqrestore+0x20/0x40
[40.599787] drv_start+0x35/0x110 [mac80211]
[40.599817] ieee80211_do_open+0x302/0x8f0 [mac80211]
[40.599844] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[40.599851] __dev_open+0xc2/0x140
[40.599862] ? _raw_spin_lock_bh+0x13/0x40
[40.599868] __dev_change_flags+0x1a7/0x1e0
[40.599883] ? ___sys_recvmsg+0x188/0x230
[40.599889] dev_change_flags+0x23/0x60
[40.599899] devinet_ioctl+0x5f9/0x6b0
[40.599907] ? sock_do_ioctl+0x20/0x50
[40.599910] sock_do_ioctl+0x20/0x50
[40.599915] sock_ioctl+0x1ed/0x2b0
[40.599919] do_vfs_ioctl+0x9f/0x610
[40.599925] ? __sys_recvmsg+0x4e/0x90
[40.599930] ? __sys_recvmsg+0x4e/0x90
[40.599934] SyS_ioctl+0x74/0x80
[40.599940] system_call_fast_compare_end+0xc/0x6f
[40.599944] RIP: 0033:0x7faa895b6d97
[40.599947] RSP: 002b:00007ffd33717a38 EFLAGS: 00000246
[40.817891] iwlwifi 0000:03:00.0: Microcode SW error detected. Restarting 0x82000000.
[40.818074] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[40.818081] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 6
[40.818086] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[40.818092] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[40.818096] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[40.818100] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[40.818104] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[40.818109] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[40.818113] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[40.818117] iwlwifi 0000:03:00.0: 0x00000002 | data1
[40.818121] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[40.818124] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[40.818128] iwlwifi 0000:03:00.0: 0x003F9F7F | beacon time
[40.818132] iwlwifi 0000:03:00.0: 0x0000607F | tsf low
[40.818136] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[40.818139] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[40.818143] iwlwifi 0000:03:00.0: 0x00006080 | time gp2
[40.818147] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[40.818151] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[40.818154] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[40.818158] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[40.818162] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[40.818165] iwlwifi 0000:03:00.0: 0x001E0405 | hcmd
[40.818169] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[40.818173] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[40.818177] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[40.818180] iwlwifi 0000:03:00.0: 0x00400080 | isr3

[40.818184] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[40.818187] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[40.818191] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[40.818195] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[40.818199] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[40.818203] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[40.818206] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[40.818210] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[40.818213] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[40.818218] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[40.818442] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[40.818449] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 7
[40.818455] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[40.818460] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[40.818465] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[40.818471] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[40.818477] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[40.818482] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[40.818488] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[40.818493] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[40.818499] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[40.818504] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[40.818510] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[40.818514] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[40.818518] iwlwifi 0000:03:00.0: 0x001E0405 | last host cmd
[40.818521] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[40.818530] ieee80211 phy11: Hardware restart was requested
[40.818570] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[40.818585] CPU: 5 PID: 677 Comm: wpa_supplicant Tainted: P   W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[40.818588] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[40.818590] Call Trace:
[40.818607] dump_stack+0x5c/0x85
[40.818632] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[40.818642] ? remove_wait_queue+0x60/0x60
[40.818662] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[40.818685] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[40.818704] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[40.818722] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[40.818735] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[40.818745] ? preempt_count_add+0x56/0xa0
[40.818762] __iwl_mvm_mac_start+0x2d5/0x350 [iwlmvm]
[40.818778] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[40.818785] ? chrdev_open+0xaf/0x1f0
[40.818834] drv_start+0x35/0x110 [mac80211]
[40.818873] ieee80211_do_open+0x302/0x8f0 [mac80211]
[40.818910] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[40.818921] __dev_open+0xc2/0x140
[40.818930] ? _raw_spin_lock_bh+0x13/0x40
[40.818937] __dev_change_flags+0x1a7/0x1e0
[40.818946] dev_change_flags+0x23/0x60
[40.818952] devinet_ioctl+0x5f9/0x6b0

[40.818960] ? __cache_free+0x31/0x2e0
[40.818970] ? sock_do_ioctl+0x20/0x50
[40.818975] sock_do_ioctl+0x20/0x50
[40.818982] sock_ioctl+0x1ed/0x2b0
[40.818989] do_vfs_ioctl+0x9f/0x610
[40.818998] ? vfs_read+0x91/0x130
[40.819005] SyS_ioctl+0x74/0x80
[40.819014] system_call_fast_compare_end+0xc/0x6f
[40.819020] RIP: 0033:0x7faa895b6d97
[40.819024] RSP: 002b:00007ffd337178c8 EFLAGS: 00000246
[40.966466] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-34.ucode (-2)
[40.966471] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-34.ucode failed with error -2
[40.966480] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-33.ucode (-2)
[40.966482] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-33.ucode failed with error -2
[40.966490] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-32.ucode (-2)
[40.966492] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-32.ucode failed with error -2
[40.966499] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-31.ucode (-2)
[40.966501] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-31.ucode failed with error -2
[40.966508] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-30.ucode (-2)
[40.966510] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-30.ucode failed with error -2
[40.966517] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-29.ucode (-2)
[40.966519] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-29.ucode failed with error -2
[40.966526] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-28.ucode (-2)
[40.966528] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-28.ucode failed with error -2
[40.966535] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-27.ucode (-2)
[40.966537] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-27.ucode failed with error -2
[40.966544] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-26.ucode (-2)
[40.966546] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-26.ucode failed with error -2
[40.966553] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-25.ucode (-2)
[40.966555] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-25.ucode failed with error -2
[40.966563] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-24.ucode (-2)
[40.966564] iwlwifi 0000:03:00.0: Direct firmware load for

iwlwifi-8265-24.ucode failed with error -2
[40.966571] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-23.ucode (-2)
[40.966573] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-23.ucode failed with error -2
[40.967120] iwlwifi 0000:03:00.0: firmware: direct-loading firmware iwlwifi-8265-22.ucode
[40.967719] iwlwifi 0000:03:00.0: loaded firmware version 22.361476.0 op_mode iwlmvm
[40.967733] iwlwifi 0000:03:00.0: Detected Intel(R) Dual Band Wireless AC 8265, REV=0x230
[41.025140] iwlwifi 0000:03:00.0: base HW address: f8:34:41:07:39:a1
[41.102109] ieee80211 phy12: Selected rate control algorithm 'iwl-mvm-rs'
[41.104371] (NULL device *): hwmon_device_register() is deprecated. Please convert the driver to use hwmon_device_register_with_info().
[41.104425] thermal thermal_zone12: failed to read out thermal zone (-61)
[41.111562] iwlwifi 0000:03:00.0 wlp3s0: renamed from wlan0
[41.157060] IPv6: ADDRCONF(NETDEV_UP): wlp3s0: link is not ready
[41.353172] iwlwifi 0000:03:00.0: Microcode SW error detected. Restarting 0x2000000.
[41.353346] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[41.353347] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 6
[41.353348] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[41.353349] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[41.353350] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[41.353351] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[41.353352] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[41.353353] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[41.353354] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[41.353355] iwlwifi 0000:03:00.0: 0x00000002 | data1
[41.353356] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[41.353357] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[41.353358] iwlwifi 0000:03:00.0: 0x003FBD8A | beacon time
[41.353359] iwlwifi 0000:03:00.0: 0x00004275 | tsf low
[41.353359] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[41.353360] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[41.353361] iwlwifi 0000:03:00.0: 0x00004276 | time gp2
[41.353362] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[41.353363] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[41.353364] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[41.353365] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[41.353366] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[41.353367] iwlwifi 0000:03:00.0: 0x00200405 | hcmd
[41.353367] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[41.353368] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[41.353369] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[41.353370] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[41.353371] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[41.353372] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[41.353373] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[41.353374] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[41.353375] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[41.353376] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid

[41.353376] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[41.353377] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[41.353378] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[41.353379] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[41.353542] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[41.353543] iwlwifi 0000:03:00.0: Status: 0x00000100, count: 7
[41.353544] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[41.353545] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[41.353546] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[41.353547] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[41.353547] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[41.353548] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[41.353549] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[41.353550] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[41.353551] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[41.353552] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[41.353553] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[41.353554] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[41.353554] iwlwifi 0000:03:00.0: 0x00200405 | last host cmd
[41.353555] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[41.353557] ieee80211 phy12: Hardware restart was requested
[41.353563] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[41.353566] CPU: 5 PID: 612 Comm: NetworkManager Tainted: P   W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[41.353567] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[41.353568] Call Trace:
[41.353573] dump_stack+0x5c/0x85
[41.353579] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[41.353582] ? remove_wait_queue+0x60/0x60
[41.353586] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[41.353591] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[41.353595] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[41.353598] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[41.353600] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[41.353602] ? preempt_count_add+0x56/0xa0
[41.353605] __iwl_mvm_mac_start+0x2d5/0x350 [iwlmvm]
[41.353608] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[41.353626] drv_start+0x35/0x110 [mac80211]
[41.353635] ieee80211_do_open+0x302/0x8f0 [mac80211]
[41.353642] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]
[41.353645] __dev_open+0xc2/0x140
[41.353647] ? _raw_spin_lock_bh+0x13/0x40
[41.353649] __dev_change_flags+0x1a7/0x1e0
[41.353650] dev_change_flags+0x23/0x60
[41.353653] do_setlink+0x324/0xcc0
[41.353655] ? __kmalloc_reserve.isra.37+0x2e/0x80
[41.353657] ? pskb_expand_head+0xe1/0x2b0
[41.353658] ? ___cache_free+0x31/0x2e0
[41.353660] ? __local_bh_enable_ip+0x3f/0x70
[41.353661] ? inet6_fill_ifla6_attrs+0x451/0x470
[41.353663] rtnl_newlink+0x7f6/0x920
[41.353664] ? sock_def_readable+0xe/0x70

[41.353666] ? __netlink_sendskb+0x47/0x60
[41.353670] ? ttwu_stat+0x110/0x120
[41.353671] ? _raw_write_unlock_bh+0x20/0x20
[41.353672] ? security_capable+0x41/0x60
[41.353674] rtnetlink_rcv_msg+0x17e/0x2b0
[41.353676] ? rtnl_calcit.isra.26+0x120/0x120
[41.353678] netlink_rcv_skb+0xe7/0x120
[41.353681] netlink_unicast+0x1a8/0x250
[41.353683] netlink_sendmsg+0x2cb/0x3c0
[41.353686] sock_sendmsg+0x30/0x40
[41.353689] ___sys_sendmsg+0x2d7/0x2f0
[41.353692] ? __do_proc_dointvec+0x2ec/0x3f0
[41.353693] ? __rtnl_unlock+0x25/0x40
[41.353694] ? netdev_run_todo+0x61/0x310
[41.353695] ? ___cache_free+0x31/0x2e0
[41.353697] ? preempt_count_add+0x56/0xa0
[41.353698] ? _raw_spin_lock+0x13/0x40
[41.353705] ? lockref_put_or_lock+0x5a/0x80
[41.353712] ? dput+0x16e/0x200
[41.353713] ? __sys_sendmsg+0x51/0x90
[41.353714] __sys_sendmsg+0x51/0x90
[41.353719] system_call_fast_compare_end+0xc/0x6f
[41.353723] RIP: 0033:0x7f6e7a67de90
[41.353724] RSP: 002b:00007ffc44ad0b20 EFLAGS: 00000293
[42.892915] atkbd serio0: Unknown key pressed (translated set 2, code 0xf8 on isa0060/serio0).
[42.892916] atkbd serio0: Use 'setkeycodes e078 <keycode>' to make it known.
[43.112685] iwlwifi 0000:03:00.0: Microcode SW error detected. Restarting 0x82000000.
[43.112846] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[43.112850] iwlwifi 0000:03:00.0: Status: 0x00000110, count: 6
[43.112854] iwlwifi 0000:03:00.0: Loaded firmware version: 22.361476.0
[43.112858] iwlwifi 0000:03:00.0: 0x00000038 | BAD_COMMAND
[43.112861] iwlwifi 0000:03:00.0: 0x00A002F0 | trm_hw_status0
[43.112864] iwlwifi 0000:03:00.0: 0x00000000 | trm_hw_status1
[43.112867] iwlwifi 0000:03:00.0: 0x0000E258 | branchlink2
[43.112870] iwlwifi 0000:03:00.0: 0x0002730C | interruptlink1
[43.112873] iwlwifi 0000:03:00.0: 0x00000000 | interruptlink2
[43.112876] iwlwifi 0000:03:00.0: 0x00000002 | data1
[43.112879] iwlwifi 0000:03:00.0: 0xDEADBEEF | data2
[43.112882] iwlwifi 0000:03:00.0: 0xDEADBEEF | data3
[43.112884] iwlwifi 0000:03:00.0: 0x003FA31A | beacon time
[43.112887] iwlwifi 0000:03:00.0: 0x00005CE4 | tsf low
[43.112890] iwlwifi 0000:03:00.0: 0x00000000 | tsf hi
[43.112893] iwlwifi 0000:03:00.0: 0x00000000 | time gp1
[43.112896] iwlwifi 0000:03:00.0: 0x00005CE5 | time gp2
[43.112899] iwlwifi 0000:03:00.0: 0x00000000 | uCode revision type
[43.112902] iwlwifi 0000:03:00.0: 0x00000016 | uCode version major
[43.112905] iwlwifi 0000:03:00.0: 0x00058404 | uCode version minor
[43.112908] iwlwifi 0000:03:00.0: 0x00000230 | hw version
[43.112911] iwlwifi 0000:03:00.0: 0x18C89000 | board version
[43.112914] iwlwifi 0000:03:00.0: 0x001F0405 | hcmd

[43.112917] iwlwifi 0000:03:00.0: 0x00022080 | isr0
[43.112919] iwlwifi 0000:03:00.0: 0x00000000 | isr1
[43.112922] iwlwifi 0000:03:00.0: 0x08201802 | isr2
[43.112925] iwlwifi 0000:03:00.0: 0x00400080 | isr3
[43.112928] iwlwifi 0000:03:00.0: 0x00000000 | isr4
[43.112931] iwlwifi 0000:03:00.0: 0x04000118 | last cmd Id
[43.112934] iwlwifi 0000:03:00.0: 0x00000000 | wait_event
[43.112937] iwlwifi 0000:03:00.0: 0x00009BFA | l2p_control
[43.112939] iwlwifi 0000:03:00.0: 0x00000020 | l2p_duration
[43.112942] iwlwifi 0000:03:00.0: 0x00000000 | l2p_mhvalid
[43.112945] iwlwifi 0000:03:00.0: 0x00000000 | l2p_addr_match
[43.112948] iwlwifi 0000:03:00.0: 0x0000000D | lmpm_pmg_sel
[43.112951] iwlwifi 0000:03:00.0: 0x03071928 | timestamp
[43.112954] iwlwifi 0000:03:00.0: 0x00001828 | flow_handler
[43.113121] iwlwifi 0000:03:00.0: Start IWL Error Log Dump:
[43.113124] iwlwifi 0000:03:00.0: Status: 0x00000110, count: 7
[43.113127] iwlwifi 0000:03:00.0: 0x00000070 | ADVANCED_SYSASSERT
[43.113130] iwlwifi 0000:03:00.0: 0x00000000 | umac branchlink1
[43.113133] iwlwifi 0000:03:00.0: 0xC0082F64 | umac branchlink2
[43.113136] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink1
[43.113139] iwlwifi 0000:03:00.0: 0xC0081000 | umac interruptlink2
[43.113142] iwlwifi 0000:03:00.0: 0x00000800 | umac data1
[43.113145] iwlwifi 0000:03:00.0: 0xC0081000 | umac data2
[43.113147] iwlwifi 0000:03:00.0: 0xDEADBEEF | umac data3
[43.113150] iwlwifi 0000:03:00.0: 0x00000016 | umac major
[43.113153] iwlwifi 0000:03:00.0: 0x00058404 | umac minor
[43.113156] iwlwifi 0000:03:00.0: 0xC0886280 | frame pointer
[43.113159] iwlwifi 0000:03:00.0: 0xC0886280 | stack pointer
[43.113162] iwlwifi 0000:03:00.0: 0x001F0405 | last host cmd
[43.113165] iwlwifi 0000:03:00.0: 0x00000000 | isr status reg
[43.113169] iwlwifi 0000:03:00.0: Firmware error during reconfiguration - reprobe!
[43.113197] iwlwifi 0000:03:00.0: FW error in SYNC CMD GEO_TX_POWER_LIMIT
[43.113207] CPU: 5 PID: 677 Comm: wpa_supplicant Tainted: P W O 4.14.0-deepin2-amd64 #1 Deepin 4.14.12-2
[43.113209] Hardware name: HP HP ZHAN 66 Pro G1/83FD, BIOS Q93 Ver. 01.02.09 01/26/2018
[43.113211] Call Trace:
[43.113223] dump_stack+0x5c/0x85
[43.113240] iwl_trans_pcie_send_hcmd+0x389/0x460 [iwlwifi]
[43.113248] ? remove_wait_queue+0x60/0x60
[43.113260] iwl_trans_send_cmd+0x4a/0xc0 [iwlwifi]
[43.113275] iwl_mvm_send_cmd+0x23/0x80 [iwlmvm]
[43.113286] iwl_mvm_send_cmd_pdu+0x58/0x80 [iwlmvm]
[43.113300] ? iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[43.113307] iwl_mvm_up+0x7f2/0x9a0 [iwlmvm]
[43.113316] ? iwl_mvm_channel_switch+0x10/0x10 [iwlmvm]
[43.113326] __iwl_mvm_mac_start+0x2b3/0x350 [iwlmvm]
[43.113336] iwl_mvm_mac_start+0x51/0x110 [iwlmvm]
[43.113341] ? _raw_spin_unlock_irqrestore+0x20/0x40
[43.113372] drv_start+0x35/0x110 [mac80211]
[43.113400] ieee80211_do_open+0x302/0x8f0 [mac80211]
[43.113426] ? ieee80211_check_concurrent_iface+0x11a/0x1e0 [mac80211]

[43.113432] __dev_open+0xc2/0x140
[43.113437] ? _raw_spin_lock_bh+0x13/0x40
[43.113442] __dev_change_flags+0x1a7/0x1e0
[43.113448] ? ___sys_recvmsg+0x188/0x230
[43.113454] dev_change_flags+0x23/0x60
[43.113458] devinet_ioctl+0x5f9/0x6b0
[43.113464] ? sock_do_ioctl+0x20/0x50
[43.113467] sock_do_ioctl+0x20/0x50
[43.113471] sock_ioctl+0x1ed/0x2b0
[43.113476] do_vfs_ioctl+0x9f/0x610
[43.113481] ? __sys_recvmsg+0x4e/0x90
[43.113485] ? __sys_recvmsg+0x4e/0x90
[43.113489] SyS_ioctl+0x74/0x80
[43.113495] system_call_fast_compare_end+0xc/0x6f
[43.113499] RIP: 0033:0x7faa895b6d97
[43.113502] RSP: 002b:00007ffd33717a38 EFLAGS: 00000246
[43.154556] call_modprobe: netdev-wlp3s0   2
[43.156463] call_modprobe: wlp3s0   2
[43.158385] call_modprobe: netdev-wlp3s0   2
[43.160101] call_modprobe: wlp3s0   2
[43.175173] call_modprobe: netdev-wlp3s0   2
[43.177511] call_modprobe: wlp3s0   2
[43.179796] call_modprobe: netdev-wlp3s0   2
[43.181023] call_modprobe: wlp3s0   2
[43.182353] call_modprobe: netdev-wlp3s0   2
[43.183632] call_modprobe: wlp3s0   2
[43.184928] call_modprobe: netdev-wlp3s0   2
[43.185962] call_modprobe: wlp3s0   2
[43.187030] call_modprobe: netdev-wlp3s0   2
[43.187925] call_modprobe: wlp3s0   2
[43.188728] call_modprobe: netdev-wlp3s0   2
[43.189549] call_modprobe: wlp3s0   2
[43.190774] call_modprobe: netdev-wlp3s0   2
[43.192206] call_modprobe: wlp3s0   2
[43.193418] call_modprobe: netdev-wlp3s0   2
[43.196082] call_modprobe: wlp3s0   2
[43.197258] call_modprobe: netdev-wlp3s0   2
[43.198314] call_modprobe: wlp3s0   2
[43.199173] call_modprobe: netdev-wlp3s0   2
[43.199983] call_modprobe: wlp3s0   2
[43.200024] atkbd serio0: Unknown key released (translated set 2, code 0xf8 on isa0060/serio0).
[43.200027] atkbd serio0: Use 'setkeycodes e078 <keycode>' to make it known.
[43.200855] call_modprobe: netdev-wlp3s0   2
[43.201707] call_modprobe: wlp3s0   2
[43.202557] call_modprobe: netdev-wlp3s0   2
[43.203730] call_modprobe: wlp3s0   2
[43.204881] call_modprobe: netdev-wlp3s0   2
[43.205523] call_modprobe: wlp3s0   2
[43.206166] call_modprobe: netdev-wlp3s0   2
[43.206772] call_modprobe: wlp3s0   2
[43.207405] call_modprobe: netdev-wlp3s0   2

[43.207963] call_modprobe: wlp3s0 2
[43.208512] call_modprobe: netdev-wlp3s0 2
[43.209081] call_modprobe: wlp3s0 2
[43.209708] call_modprobe: netdev-wlp3s0 2
[43.210234] call_modprobe: wlp3s0 2
[43.210823] wpa_supplicant[677]: segfault at 0 ip 000055da5058f6b1 sp 00007ffd33718150 error 4 in wpa_supplicant[55da50464000+1fe000]
[43.277990] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-34.ucode (-2)
[43.277996] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-34.ucode failed with error -2
[43.278006] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-33.ucode (-2)
[43.278008] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-33.ucode failed with error -2
[43.278015] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-32.ucode (-2)
[43.278017] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-32.ucode failed with error -2
[43.278025] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-31.ucode (-2)
[43.278027] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-31.ucode failed with error -2
[43.278034] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-30.ucode (-2)
[43.278036] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-30.ucode failed with error -2
[43.278043] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-29.ucode (-2)
[43.278045] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-29.ucode failed with error -2
[43.278052] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-28.ucode (-2)
[43.278054] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-28.ucode failed with error -2
[43.278061] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-27.ucode (-2)
[43.278063] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-27.ucode failed with error -2
[43.278071] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-26.ucode (-2)
[43.278072] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-26.ucode failed with error -2
[43.278080] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-25.ucode (-2)
[43.278081] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-25.ucode failed with error -2
[43.278089] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-24.ucode (-2)
[43.278090] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-24.ucode failed with error -2
[43.278098] iwlwifi 0000:03:00.0: firmware: failed to load iwlwifi-8265-23.ucode (-2)

[43.278099] iwlwifi 0000:03:00.0: Direct firmware load for iwlwifi-8265-23.ucode failed with error -2
[43.278654] iwlwifi 0000:03:00.0: firmware: direct-loading firmware iwlwifi-8265-22.ucode
[43.279214] iwlwifi 0000:03:00.0: loaded firmware version 22.361476.0 op_mode iwlmvm
[43.279227] iwlwifi 0000:03:00.0: Detected Intel(R) Dual Band Wireless AC 8265, REV=0x230
[43.336201] iwlwifi 0000:03:00.0: base HW address: f8:34:41:07:39:a1
[43.413060] ieee80211 phy13: Selected rate control algorithm 'iwl-mvm-rs'
[43.413420] (NULL device *): hwmon_device_register() is deprecated. Please convert the driver to use hwmon_device_register_with_info().
[43.413450] thermal thermal_zone12: failed to read out thermal zone (-61)
[43.416815] iwlwifi 0000:03:00.0 wlp3s0: renamed from wlan0
[43.456853] IPv6: ADDRCONF(NETDEV_UP): wlp3s0: link is not ready
[1765.265699] usb 1-4: new high-speed USB device number 6 using xhci_hcd
[1765.414824] usb 1-4: New USB device found, idVendor=0e8d, idProduct=2008
[1765.414831] usb 1-4: New USB device strings: Mfr=3, Product=4, SerialNumber=5
[1765.414835] usb 1-4: Product: M5 Note
[1765.414838] usb 1-4: Manufacturer: MediaTek
[1765.414841] usb 1-4: SerialNumber: 621QECQ93RQJJ
[1825.725336] usb 1-4: reset high-speed USB device number 6 using xhci_hcd
[1826.009398] usb 1-4: reset high-speed USB device number 6 using xhci_hcd